



# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451 Page Number : D1 of D2
Report Issued Date : Aug. 09, 2017
Report Version : Rev. 01

Report No.: FR731002-01C


Report Template No.: BU5-FR15CWL Version 1.3



### <Radiated Emission>

#### X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451 Page Number : D2 of D2
Report Issued Date : Aug. 09, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR731002-01C