Appendix A. Setup Photographs

<Conducted Emission>

Mode 1






Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : A1 of A4
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01


Report No. : FC7O1703

Report Template No.: BU5-FC15B Version 1.3



Mode 3





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: 2ALTA362X Page Number : A2 of A4
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 1

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : A3 of A4
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No. : FC7O1703

Mode 3

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : A4 of A4
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7O1703