1. External Photograph of EUT

Brand Name: Mint; Model Name: M355

Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 1 of 44
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01




Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X

Page Number : 2 of 44 Report Issued Date : Jul. 12, 2017





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 3 of 44
Report Issued Date : Jul. 12, 2017

Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 4 of 44
Report Issued Date : Jul. 12, 2017



Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X


Page Number : 5 of 44

Report Issued Date : Jul. 12, 2017

Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 6 of 44
Report Issued Date : Jul. 12, 2017



2. Photograph of Accessory

Brand Name: Mint; Model Name: M355

Report No.: EP762205

List of Accessory:


Specification of Accessory		
IAC Adapter	Brand Name	DongChen
	Model Name	DCS10-0501000F
IBattery	Brand Name	Guizhou aerospace
	Model Name	PLV346488
USB Cable	Signal Line Type	1.0m, shielded cable, without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON International (ShenZhen) INC.Page NumberTEL: 86-755-8637-9589Report Issued Date

FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 7 of 44
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report No.: EP762205



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 8 of 44
Report Issued Date : Jul. 12, 2017



Report No.: EP762205




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X

Page Number : 9 of 44 Report Issued Date : Jul. 12, 2017



Report No.: EP762205




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 10 of 44
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 11 of 44
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : 12 of 44
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01