

Report No.:FR771706B

## Appendix D. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : D1 of D2
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0 Version 2.0




## Report No.:FR771706B

## <Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : D2 of D2
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0