



## Report No.: FR731002-01B

# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451

Page Number : D1 of D2 Report Issued Date: Aug. 09, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3




## <Radiated Emission>

#### X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451 Page Number : D2 of D2 Report Issued Date : Aug. 09, 2017

Report No.: FR731002-01B

Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3