
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for Part 22H

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : C1 of C2
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.2


Report No. : FG7O1703

X Plane for Part 24E

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : C2 of C2
Report Issued Date : Nov. 07, 2017
Report Version : Rev. 01

Report No. : FG7O1703

Report Template No.: BU5-FG22/24 Version 1.2