Appendix A. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589
FAX: +86-755-8637-9595
FCC ID: 2ALTA300X

Page Number : A1 of A3
Report Issued Date : Sep. 07, 2017
Report Version : Rev. 01


Report No. : FC782106

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 1

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA300X Page Number : A2 of A3
Report Issued Date : Sep. 07, 2017
Report Version : Rev. 01

Report No.: FC782106


Report Template No.: BU5-FC15B Version 1.3

Mode 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA300X Page Number : A3 of A3
Report Issued Date : Sep. 07, 2017
Report Version : Rev. 01

Report No.: FC782106

Report Template No.: BU5-FC15B Version 1.3