
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : C1 of C2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.2

Report No.: FG762205A

Z Plane for 24E

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : C2 of C2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.2

Report No. : FG762205A