# Appendix A. Setup Photographs

## <Conducted Emission>

## Mode 2





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : A1 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC762108



Mode 3





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : A2 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC762108


## <Radiated Emission>

## Mode 1

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : A3 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC762108


C Test Report No. : FC762108

## Mode 3

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : A4 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3