


Report No. : FR740606-01C

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 1 of 3
Report Issued Date : Aug. 28, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 2.0





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 2 of 3
Report Issued Date : Aug. 28, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL MA Version 2.0




Report No.: FR740606-01C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 3 of 3
Report Issued Date : Aug. 28, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 2.0