

Setup Photographs

<Conducted Emission>

Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 1 of 3
Report Issued Date : Aug. 22, 2017
Report Version : Rev. 01

Report No.: FR740606-01D

Report Template No.: BU5-FR15EWL AC MA Version 2.0







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 2 of 3
Report Issued Date : Aug. 22, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15EWL AC MA Version 2.0

<Radiated Emission>



Report No.: FR740606-01D

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALWB-7232 Page Number : 3 of 3 Report Issued Date : Aug. 22, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 2.0