



REPORT No. : SZ19100008W02


Band4 / 5MHz / Low CH / QPSK




Band4 / 5MHz / Low CH / 16QAM




Band4 / 5MHz / Mid CH / QPSK




Band4 / 5MHz / Mid CH / 16QAM



Band4 / 5MHz / High CH / QPSK



Band4 / 5MHz / High CH / 16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No. : SZ19100008W02

Band4 / 10MHz / Low CH / QPSK




Band4 / 10MHz / Low CH / 16QAM




Band4 / 10MHz / Mid CH / QPSK




Band4 / 10MHz / Mid CH / 16QAM



Band4 / 10MHz / High CH / QPSK



Band4 / 10MHz / High CH / 16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




Band4 / 15MHz / Low CH / QPSK




Band4 / 15MHz / Low CH / 16QAM




Band4 / 15MHz / Mid CH / QPSK




Band4 / 15MHz / Mid CH / 16QAM



Band4 / 15MHz / High CH / QPSK




Band4 / 15MHz / High CH / 16QAM







Band4 / 20MHz / Low CH / QPSK




Band4 / 20MHz / Low CH / 16QAM




Band4 / 20MHz / Mid CH / QPSK




Band4 / 20MHz / Mid CH / 16QAM





Band4 / 20MHz / High CH / QPSK




Band4 / 20MHz / High CH / 16QAM



Band5 / 1.4MHz / Low CH / QPSK

Band5 / 1.4MHz / Low CH / 16QAM

Band5 / 1.4MHz / Mid CH / QPSK

Band5 / 1.4MHz / Mid CH / 16QAM


Band5 / 1.4MHz / High CH / QPSK

Band5 / 1.4MHz / High CH / 16QAM





Band5 / 3MHz / Low CH / QPSK




Band5 / 3MHz / Low CH / 16QAM




Band5 / 3MHz / Mid CH / QPSK




Band5 / 3MHz / Mid CH / 16QAM



Band5 / 3MHz / High CH / QPSK




Band5 / 3MHz / High CH / 16QAM





REPORT No. : SZ19100008W02


Band5 / 5MHz / Low CH / QPSK



Band5 / 5MHz / Low CH / 16QAM




Band5 / 5MHz / Mid CH / QPSK




Band5 / 5MHz / Mid CH / 16QAM



Band5 / 5MHz / High CH / QPSK



Band5 / 5MHz / High CH / 16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No. : SZ19100008W02


Band5 / 10MHz / Low CH / QPSK



Band5 / 10MHz / Low CH / 16QAM




Band5 / 10MHz / Mid CH / QPSK



Band5 / 10MHz / Mid CH / 16QAM



Band5 / 10MHz / High CH / QPSK



Band5 / 10MHz / High CH / 16QAM






Band12 / 1.4MHz / Low CH / QPSK



Band12 / 1.4MHz / Low CH / 16QAM



Band12 / 1.4MHz / Mid CH / QPSK




Band12 / 1.4MHz / Mid CH / 16QAM



Band12 / 1.4MHz / High CH / QPSK



Band12 / 1.4MHz / High CH / 16QAM






REPORT No. : SZ19100008W02

Band12 / 3MHz / Low CH / QPSK



Band12 / 3MHz / Low CH / 16QAM



Band12 / 3MHz / Mid CH / QPSK



Band12 / 3MHz / Mid CH / 16QAM



Band12 / 3MHz / High CH / QPSK




Band12 / 3MHz / High CH / 16QAM






REPORT No. : SZ19100008W02

Band12 / 5MHz / Low CH / QPSK



Band12 / 5MHz / Low CH / 16QAM




Band12 / 5MHz / Mid CH / QPSK




Band12 / 5MHz / Mid CH / 16QAM



Band12 / 5MHz / High CH / QPSK




Band12 / 5MHz / High CH / 16QAM





REPORT No. : SZ19100008W02


Band12 / 10MHz / Low CH / QPSK




Band12 / 10MHz / Low CH / 16QAM




Band12 / 10MHz / Mid CH / QPSK




Band12 / 10MHz / Mid CH / 16QAM



Band12 / 10MHz / High CH / QPSK



Band12 / 10MHz / High CH / 16QAM





REPORT No. : SZ19100008W02


Band13 / 5MHz / Low CH / QPSK




Band13 / 5MHz / Low CH / 16QAM




Band13 / 5MHz / Mid CH / QPSK




Band13 / 5MHz / Mid CH / 16QAM



Band13 / 5MHz / High CH / QPSK



Band13 / 5MHz / High CH / 16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No. : SZ19100008W02


Band13 / 10MHz / Mid CH / QPSK



Band13 / 10MHz / Mid CH / 16QAM




Band17 / 5MHz / Low CH / QPSK



Band17 / 5MHz / Low CH / 16QAM



Band17 / 5MHz / Mid CH / QPSK



Band17 / 5MHz / Mid CH / 16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn