Test report No.
 : 12985473H-R2

 Page
 : 26 of 28

 Issued date
 : October 23, 2019

 FCC ID
 : 2AM4XZERS01

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

(Below 1 GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12985473H-R2 : 27 of 28 Page : October 23, 2019 : 2AM4XZERS01 Issued date FCC ID

Radiated Spurious Emission (Above 1 GHz)



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 12985473H-R2

 Page
 : 28 of 28

 Issued date
 : October 23, 2019

 FCC ID
 : 2AM4XZERS01

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124