Servicios Troncalizados S.A. de C.V.

Av. Revolucion 639 piso 4 Col. San Pedro de los Pinos CP 03800, Mexico City Mexico

September 9, 2019

FEDERAL COMMUNICATIONS COMMISSION AUTHORIZATION AND EVALUATION DIVISION 7435 OAKLAND MILLS ROAD COLUMBIA, MD 21046

SUBJECT: FCCID: 2AM58-TVX887PLUS

TO WHOM IT MAY CONCERN:

We place the FCC label in the battery compartment due to below reasons:

- 1. The FCC label is visible when user open the battery door and install the batteries, otherwise, the equipment doesn't work.
- 2. The equipment is separated from the battery and the cover in the packing box, users can read the FCC ID information at the time of purchase.
- 3. Label placed on the exterior of the equipment affect the appearance according to design requirements; otherwise, it would be easily removed or damaged.

BEST REGARDS,

Servicios Troncalizados S.A. de C.V.

(Ragnar Trillo) (Manager)