





Ensure the IC interface is facing towards.

1. Check if the printer paper cover is fully closed.

2. Ensure the paper roll is installed correctly.

to the right position.

IV. Printer not working

and Restart

2. Check if there is foreign objects blocked in the slot or if IC card is inserted



- The author of this manual is Fujian Newland Payment Technology Co., LTD. According to Copyright Law of the People's Republic of China, the author benefits and reserves all the copyrights and other exclusive rights. Without the permission of the copyright owner, it is not allowed to copy, add or subtract, excerpt, reproduce or imitate partial or whole of this The content of this manual is to instruct users to use the product correctly. Regarding on the content of this manual, Fujian Newland Payment Technology Co., LTD disclaims any responsibility for any express or implied assurance. For any damage/issue caused by using unauthorized accessory or
 - interference that may cause undesired operation. This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures: 1. Reorient or relocate the receiving antenna. 2. Increase the separation between the equipment and receiver.

1. This device may not cause harmful interference.

2. This device must accept any interference received, including

3. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected. 4. Consult the dealer or an experienced radio/TV technician for help. Specific Absorption Rate (SAR) information

SAR tests are conducted using standard operating positions accepted

by the FCC with the device transmitting at its highest certified power

- level in all tested frequency bands, although the SAR is determined at the highest certified power level, the actual SAR level of the device while operating can be well below the maximum value. Before a new product is a available for sale to the public, it must be tested and certified to the FCC that it does not exceed the exposure limit established by the FCC, tests for each product are performed in positions and locations as required by the FCC.
- Forbody-worn/handheld operation, this model product has been consumable (not provided or approved by Newland), Newland holds no tested andmeets the FCC RFexposure guidelines when used with an responsibility. Without the permission of Newland, it is not allowed to accessory designated for this product orwhen used with an accessory modify or change newland product. that Contains no metal. Any Changes or modifications not expressly approved by the party
- responsible for compliance could void the user's authority to operate the In case of product update, the detail of the manual may mismatch with This device complies with part 15 of the FCC Rules. the product. The product shall prevail. We reserve the right to correct and/or update any content in this manual without notice. Operation is subject to the following two conditions:

 - Enterprise product standard number: Q/FXZF 001 Fujian Newland Payment Technology Co., LTD
 - Fujian Newland Computer Technology Co., LTD Post code: 350015
 - Fax: 0591-83979955 Customer Service: 400-918-1311 Website: www.newlandpayment.com
 - Newland Science and Technology Park, No.1 Rujiang Xi Rd, Maiwei Dist, Fuzhou, Fujian, China ©Copyright Fujian Newland Payment Technology Co., LTD



