

Appendix A. TEST PHOTOS

1 Photographs of Radiated Emissions Test Configuration For radiated emission below 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






CLOSE VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973

For radiated emission above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.

: A3 of A4

Report Version

: Rev. 01





CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973