Test Photos Report No. : FR330601

Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR330601



SIDE VIEW



CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




Report No.: FR330601

Photographs of Radiated Emissions Test Configuration 2 For radiated emission below 1GHz



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01

Test Photos Report No. : FR330601

For radiated emission above 1GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR330601



CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01