

Test Photos Report No. : FR330553-03

## **Appendix A. TEST PHOTOS**

1 Photographs of Radiated Emissions Test Configuration For radiated emission below 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR330553-03




**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01




Test Photos Report No. : FR330553-03

## For radiated emission above 1GHz



FRONT VIEW




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No.: FR330553-03



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01