
Report No. : FR330553

Appendix A. TEST PHOTOS
Photographs of Radiated Emissions Test Configuration
For radiated emission below 1GHz 1



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973

Test Photos Report No. : FR330553

For radiated emission above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973