Test Photos Report No. : FR393006

## **Appendix A. TEST PHOTOS**

## 1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR393006



SIDE VIEW






**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01




Report No. : FR393006

## **Photographs of Radiated Emissions Test Configuration** 2 For radiated emission



FRONT VIEW




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR393006



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01