

Test Photos Report No. : FR401516

## **Appendix A. TEST PHOTOS**

## 1 Photographs of Radiated Emissions Test Configuration



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



Test Photos Report No. : FR4O1516



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973