Appendix A. Photographs of EUT

Please refer to Sporton report number EP170707-02 as below.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 IC: 4609A-9000WBV1 Page Number : A1 of A1
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No. : CI170707-02

1. External Photograph of EUT

Brand Name: DAP / Model Name: 9000WBV1 / Marketing Name: M9010

Report No.: EP170707-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 1 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 2 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: DAP / Model Name: 9000WBV1 / Marketing Name: M9010

Report No.: EP170707-02

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	CINCON ELECTRONICS
	Model Name	TRG36A15 12E03
Battery 1	Brand Name	DAP
	Model Name	VE026-8034
Battery 2	Brand Name	DAP
	Model Name	VE026-8035
LCD Panel	Brand Name	SGD
	Model Name	GNTW70NNBA1E0
Camera 1	Brand Name	DEMARREN
	Model Name	Q5M03A
WLAN Module	Brand Name	Summit Data Communications
	Model Name	SDC-PE15N
Bluetooth Module	Brand Name	Bluegiga
	Model Name	WT21-A
Power Cord 1	Brand Name	QUAIL
	Model Name	1062.079(NAM032)
Power Cord 2	Brand Name	QUAIL
	Model Name	8002.079(NAM033)
Power Cord 3	Brand Name	QUAIL
	Model Name	9657.079(NAM034)

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 3 of 15
Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01



Report No.: EP170707-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1

Page Number : 4 of 15 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01


otographs of EUT Report No.: EP170707-02

Brand Name: DAP / Model Name: 9000WBV1 / Marketing Name: M9010



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 5 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 6 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 7 of 15
Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

3. Internal Photograph of EUT

Brand Name: DAP / Model Name: 9000WBV1 / Marketing Name: M9010


Report No.: EP170707-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 8 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 9 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 10 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 11 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 12 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

EUT Report No.: EP170707-02




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 13 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707-02




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1

Page Number : 14 of 15 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01

Report No.: EP170707-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBV1 IC: 4609A-9000WBV1 Page Number : 15 of 15
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01