1. External Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 1 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 2 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010

Report No.: EP170707

List of Accessory:

| Specification of Accessory | | |
|----------------------------|------------|----------------------------|
| AC Adapter | Brand Name | CINCON ELECTRONICS |
| | Model Name | TRG36A15 12E03 |
| Battery 1 | Brand Name | DAP |
| | Model Name | VE026-8034 |
| Battery 2 | Brand Name | DAP |
| | Model Name | VE026-8035 |
| LCD Panel | Brand Name | SGD |
| | Model Name | GNTW70NNBA1E0 |
| Camera 1 | Brand Name | DEMARREN |
| | Model Name | Q5M03A |
| WWAN Module | Brand Name | Sierra Wireless |
| | Model Name | MC8355 |
| WLAN Module | Brand Name | Summit Data Communications |
| | Model Name | SDC-PE15N |
| Bluetooth Module | Brand Name | Bluegiga |
| | Model Name | WT21-A |
| Zigbee Module | Brand Name | Atmel |
| | Model Name | ATmega128RFA1 |
| Power Cord 1 | Brand Name | QUAIL |
| | Model Name | 1062.079(NAM032) |
| Power Cord 2 | Brand Name | QUAIL |
| | Model Name | 8002.079(NAM033) |
| Power Cord 3 | Brand Name | QUAIL |
| | Model Name | 9657.079(NAM034) |

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456

FAX: 886-3-328-4978

FCC ID: T5M9000WBWZV1

IC: 4609A-9000WBWZV1

Page Number : 3 of 23 Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 4 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 5 of 23 Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 6 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 7 of 23 Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

3. Internal Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010


Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 8 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 9 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 10 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 11 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01



Report No.: EP170707



TEL: 886-3-327-3456

FAX: 886-3-328-4978


FCC ID: T5M9000WBWZV1

IC: 4609A-9000WBWZV1

Page Number : 12 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01




Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 13 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01


Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 14 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 15 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 16 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01




Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 17 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01


Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 18 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 19 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 20 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 21 of 23
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 22 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 23 of 23 Report Issued Date : Oct. 24, 2011 Report Version : Rev. 01



Appendix B. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : B1 of B3
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01


Report No.: FR170707C





<Radiated Emission>

LF




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : B2 of B3
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: FR170707C



Report No.: FR170707C





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : B3 of B3
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01