# **Variant FCC Test Report**

APPLICANT : DAP Technologies

**EQUIPMENT** : Rugged Mobile Tablet Computer

**BRAND NAME** : DAP

MODEL NAME : 9000WBWV1

MARKETING NAME : M9010

**FCC ID** : T5M9000WBWV1

STANDARD : FCC 47 CFR FCC Part 15 Subpart B

CLASSIFICATION : Declaration of Conformity

This is a variant report which is only valid together with the original test report. The product was received on Jul. 07, 2011 and completely tested on Sep. 19, 2011. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the procedures given in ANSI C63.4-2003 and shown the compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC., the test report shall not be reproduced except in full.

Reviewed by:

Jones Tsai / Manager





Report No.: FD170707-03

#### SPORTON INTERNATIONAL INC.

No. 52, Hwa Ya 1<sup>st</sup> Rd., Hwa Ya Technology Park, Kwei-Shan Hsiang, Tao Yuan Hsien, Taiwan, R.O.C.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 1 of 21 Report Issued Date: Oct. 26, 2011

: Rev. 01 Report Version

### **TABLE OF CONTENTS**

RE	VISION	HISTORY	3
SII	IMM A R'	Y OF TEST RESULT	4
		RAL DESCRIPTION	
	1.2. 1.3. 1.4. 1.5.	Applicant  Manufacturer  Feature of Equipment Under Test  Test Site  Applied Standards  Ancillary Equipment List	5 6 7
2.	TEST	CONFIGURATION OF EQUIPMENT UNDER TEST	9
		Test Mode	
		Connection Diagram of Test System  Test Software	
3.	TEST	RESULT	11
-		Test of AC Conducted Emission Measurement	
		Test of Radiated Emission Measurement	
4.	LIST C	OF MEASURING EQUIPMENT	19
5.	UNCE	RTAINTY OF EVALUATION	20
ΑP	PENDI	X A. PHOTOGRAPHS OF EUT	
ΑP	PENDI	X B. SETUP PHOTOGRAPHS	
ΔP	PENDI	X.C. ORIGINAL REPORT	

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 2 of 21
Report Issued Date : Oct. 26, 2011
Report Various : Report 24

Report No.: FD170707-03

Report Version : Rev. 01



**REVISION HISTORY** 

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FD170707-03	Rev. 01	This is a variant report by removing Zigbee function. All the test cases were performed on original report which can be referred to Sporton Report Number FD170707 as appendix C. Based on the original report, only the worst cases of Transmitter Radiated Emissions and AC Conducted Emission Tests were verified.	Oct. 26, 2011

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 3 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



**SUMMARY OF TEST RESULT** 

Report Section	FCC Rule	IC Rule	Description	Limit	Result	Remark
3.1	15.107	7.2.4	AC Conducted Emission	< 15.107 limits < RSS-Gen table 2 limits	PASS	Under limit 6.1 dB at 26.23 MHz
3.2	15.109	7.2.3.2	Radiated Emission	< 15.109 limits or < RSS-Gen table 1 limits (Section 6)	PASS	Under limit 1.97 dB at 103.44 MHz

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 4 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

### 1. General Description

### 1.1. Applicant

**DAP Technologies** 

7450 South Priest DR Tempe, AZ, US

#### 1.2. Manufacturer

**Venture Corporation Limited** 

Blk5006, Ang Mo Kio Avenue 5, #03-07 TECHplace II, Singapore 569870

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 5 of 21
Report Issued Date : Oct. 26, 2011

Report No.: FD170707-03

Report Version : Rev. 01



1.3. Feature of Equipment Under Test

Product Feature & Specification				
Equipment	Rugged Mobile Tablet Computer			
Brand Name	DAP			
Model Name	9000WBWV1			
Marketing Name	M9010			
FCC ID	T5M9000WBWV1			
Tx Frequency Range	GSM850: 824 MHz ~ 849 MHz GSM1900: 1850 MHz ~ 1910 MHz WCDMA Band V: 824 MHz ~ 849 MHz WCDMA Band II: 1850 MHz ~ 1910 MHz WCDMA Band IV: 1710 MHz ~ 1755 MHz CDMA2000 BC0: 824 MHz ~ 849 MHz CDMA2000 BC1: 1850 MHz ~ 1910 MHz Bluetooth: 2400 MHz ~ 2483.5 MHz WLAN: 2400 MHz ~ 2483.5 MHz 5150 MHz ~ 5250 MHz 5250 MHz ~ 5350 MHz 5470 MHz ~ 5725 MHz 5725 MHz ~ 5850 MHz			
Rx Frequency Range	GSM850: 869 MHz ~ 894 MHz GSM1900: 1930 MHz ~ 1990 MHz WCDMA Band V: 869 MHz ~ 894 MHz WCDMA Band II: 1930 MHz ~ 1990 MHz WCDMA Band IV: 2110 MHz ~ 2155 MHz CDMA2000 BC0: 869 ~ 894 MHz CDMA2000 BC1: 1930 ~ 1990 MHz Bluetooth: 2400 MHz ~ 2483.5 MHz WLAN: 2400 MHz ~ 2483.5 MHz 5150 MHz ~ 5250 MHz 5250 MHz ~ 5350 MHz 5470 MHz ~ 5725 MHz 5725 MHz ~ 5850 MHz GPS: 1.57542 GHz			
Antenna Type	WWAN : Fixed Internal Antenna WLAN : PIFA Antenna Bluetooth : Chip Antenna			
HW Version	Merlion P3			
SW Version	MER_00.00.10			

 ${\it SPORTON\ INTERNATIONAL\ INC.}$ 

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 6 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

Type of Modulation	GSM / GPRS : GMSK EDGE : 8PSK WCDMA : QPSK HSDPA : QPSK / 16QAM HSUPA : BPSK CDMA2000 : QPSK Bluetooth (1Mbps) : GFSK Bluetooth EDR (2Mbps) : \pi/4-DQPSK Bluetooth EDR (3Mbps) : 8-DPSK 802.11b : DSSS (BPSK / QPSK / CCK) 802.11a/g/n : OFDM (BPSK / QPSK / 16QAM / 64QAM) GPS : BPSK
EUT Stage	Production Unit

Report No.: FD170707-03

**Remark:** The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.

#### 1.4. Test Site

Test Site	SPORTON INTERNATIONAL INC.				
	No. 52, Hwa Ya 1 <sup>st</sup> Ro	d., Hwa Ya Technology	Park,		
Took Cita Lagation	Kwei-Shan Hsiang, Tao Yuan Hsien, Taiwan, R.O.C.				
Test Site Location	TEL: +886-3-327-3456				
	FAX: +886-3-328-4978				
Took Site No	Sporton	Site No.	FCC/IC Registration No.		
Test Site No.	CO05-HY	03CH06-HY	722060/4086B-1		

### 1.5. Applied Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC 47 CFR FCC Part 15 Subpart B
- ANSI C63.4-2003
- · IC RSS-Gen Issue 3

**Remark:** All test items were verified and recorded according to the standards and without any deviation during the test.

 SPORTON INTERNATIONAL INC.
 Page Number
 : 7 of 21

 TEL: 886-3-327-3456
 Report Issued Date
 : Oct. 26, 2011

 FAX: 886-3-328-4978
 Report Version
 : Rev. 01

FCC ID: T5M9000WBWV1



1.6. Ancillary Equipment List

Item	Equipment	Trade Name	Model Name	FCC ID	Data Cable	Power Cord
1.	System Simulator	R&S	CMU 200	N/A	N/A	Unshielded, 1.8 m
2.	GPS Station	T&E	GS-50	N/A	N/A	Unshielded, 1.8 m
3.	GPS Station	pendulum	GSG-54	N/A	N/A	Unshielded, 1.8 m
4.	Bluetooth Earphone	Motorola	S705	IHDT6GH1	N/A	N/A
5.	(USB) Mouse	DELL	MOC5UO	FCC DoC	Shielded, 1.8 m	N/A
6.	(USB) Mouse	LOGITECH	M90	FCC DoC	Shielded, 1.8 m	N/A
7.	iPod Earphone	Apple	N/A	FCC DoC	Unshielded, 1.0 m	N/A

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 8 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

### 2. Test Configuration of Equipment Under Test

#### 2.1. Test Mode

The EUT has been associated with peripherals pursuant to ANSI C63.4-2003 and configuration operated in a manner tended to maximize its emission characteristics in a typical application.

Frequency range investigated: conduction (150 kHz to 30 MHz), radiation (30MHz to the 5th harmonic of the highest fundamental frequency or to 40 GHz, whichever is lower).

The EUT uses a USB interface and microprocessor operating 800MHz which is the maximum frequency used.

The following tables are showing the test modes as the worst cases and recorded in this report.

		Test Condition		
Item	EUT Configuration	EMI	EMI	
		AC	RE	
1.	Charging Mode (EUT with adapter)	$\boxtimes$	$\boxtimes$	

#### Abbreviations:

EMI AC: AC conducted emissions
 EMI RE: EUT radiated emissions

Test Items Configure Mode		Function Type
AC Conducted Emission	1	Mode 1: WCDMA Band II Idle + Bluetooth Idle + GPS Rx + TC + Adapter
Radiated Emissions	1	Mode 1: GSM850 (GPRS 8) Idle + Bluetooth Idle + GPS Rx + TC + Adapter


Remark: TC stands for Test Configuration, and consists of iPod Earphone, USB Mouse, and MPEG4..

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 9 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



2.2. Connection Diagram of Test System



#### 2.3. Test Software

The EUT was in GSM or WCDMA idle mode during the testing. The EUT was synchronized to the BCCH, and is in continuous receiving mode by setting system simulator's paging reorganization.

At the same time, the EUT was attached to the Bluetooth earphone or WLAN AP, and the following programs installed in the EUT were programmed during the test.

- 1. Execute the program, "Winthrax.exe", installed in notebook for active sync files transfer with EUT via USB cable.
- GPS, open AirCard GPS Monitor to execute "MiniGPS Lite" to make the EUT receive signals from GPS station continuously.
- 3. Execute "Video Player" to play MPEG4 files.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 10 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

#### 3. Test Result

#### 3.1. Test of AC Conducted Emission Measurement

#### 3.1.1 Limits of AC Conducted Emission

For equipment that is designed to be connected to the public utility (AC) power line, the radio frequency voltage that is conducted back onto the AC power line on any frequency or frequencies within the band 150 kHz to 30 MHz shall not exceed the limits in the following table.

Frequency of emission	Conducted	limit (dBuV)
(MHz)	Quasi-peak	Average
0.15-0.5	66 to 56*	56 to 46*
0.5-5	56	46
5-30	60	50

<sup>\*</sup>Decreases with the logarithm of the frequency.

#### 3.1.2 Measuring Instruments

See list of measuring instruments of this test report.

#### 3.1.3 Test Procedure

- 1. The EUT was placed 0.4 meter from the conducting wall of the shielding room was kept at least 80 centimeters from any other grounded conducting surface.
- 2. Connect EUT to the power mains through a line impedance stabilization network (LISN).
- 3. All the support units are connecting to the other LISN.
- 4. The LISN provides 50 ohm coupling impedance for the measuring instrument.
- 5. The FCC states that a 50 ohm, 50 microhenry LISN should be used.
- 6. Both sides of AC line were checked for maximum conducted interference.
- 7. The frequency range from 150 kHz to 30 MHz was searched.
- 8. Set the test-receiver system to Peak Detect Function and specified bandwidth with Maximum Hold Mode.


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 11 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



Report No.: FD170707-03

#### 3.1.4 Test Setup




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 12 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



3.1.5 Test Result of AC Conducted Emission

Test Mode :	Mode 1	Temperature :	<b>20~22</b> ℃	
Test Engineer :	Kai-Chun Chu	Relative Humidity :	40~42%	
Test Voltage :	120Vac / 60Hz	Phase :	Line	
Function Type :	WCDMA Band II Idle + Bluetooth Idle + GPS Rx + TC + Adapter			
Remark :	All emissions not reported here are more than 10 dB below the prescribed limit.			



#### **Final Result 1**

Frequency (MHz)	QuasiPeak (dBµV)	Filter	Line	Corr. (dB)	Margin (dB)	Limit (dBµV)
0.150000	40.4	Off	L1	19.4	25.6	66.0
0.198000	48.5	Off	L1	19.4	15.2	63.7
0.262000	40.8	Off	L1	19.4	20.6	61.4
0.326000	37.9	Off	L1	19.4	21.7	59.6
6.998000	35.5	Off	L1	19.5	24.5	60.0
26.230000	45.7	Off	L1	19.7	14.3	60.0

#### Final Result 2


Frequency	Average	Filter	Line	Corr.	Margin	Limit
(MHz)	(dBµV)	riitei	Lille	(dB)	(dB)	(dBµV)
0.150000	27.6	Off	L1	19.4	28.4	56.0
0.198000	39.8	Off	L1	19.4	13.9	53.7
0.262000	32.9	Off	L1	19.4	18.5	51.4
0.326000	30.8	Off	L1	19.4	18.8	49.6
6.998000	25.9	Off	L1	19.5	24.1	50.0
26.230000	43.9	Off	L1	19.7	6.1	50.0


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 13 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



_						
Test Mode :	Mode 1	Temperature :	20~22℃			
Test Engineer :	Kai-Chun Chu	Relative Humidity :	40~42%			
Test Voltage :	120Vac / 60Hz	Phase :	Neutral			
Function Type :	WCDMA Band II Idle + Bluetooth Idle + GPS Rx + TC + Adapter					
Remark ·	All emissions not reported here are more than 10 dR helow the prescribed limit					





#### Final Result 1

Frequency (MHz)	QuasiPeak (dBµV)	Filter	Line	Corr. (dB)	Margin (dB)	Limit (dBµV)
0.150000	41.1	Off	N	19.4	24.9	66.0
0.198000	47.7	Off	N	19.4	16.0	63.7
0.262000	41.3	Off	N	19.4	20.1	61.4
0.326000	36.6	Off	N	19.4	23.0	59.6
6.926000	36.8	Off	N	19.6	23.2	60.0
26.238000	42.2	Off	N	19.8	17.8	60.0

#### Final Result 2

•	mai itesait	_					
	Frequency	Average	Filter	Line	Corr.	Margin	Limit
	(MHz)	(dBµV)	Filler	Life	(dB)	(dB)	(dBµV)
	0.150000	27.0	Off	N	19.4	29.0	56.0
	0.198000	37.1	Off	N	19.4	16.6	53.7
	0.262000	30.1	Off	N	19.4	21.3	51.4
	0.326000	26.6	Off	N	19.4	23.0	49.6
	6.926000	25.9	Off	N	19.6	24.1	50.0
	26.238000	40.2	Off	N	19.8	9.8	50.0

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 14 of 21 Report Issued Date: Oct. 26, 2011 Report Version : Rev. 01

#### 3.2. Test of Radiated Emission Measurement

#### 3.2.1. Limit of Radiated Emission

The emissions from an intentional radiator shall not exceed the field strength levels specified in the following table:

Frequency	Field Strength	Measurement Distance		
(MHz)	(microvolts/meter)	(meters)		
0.009 – 0.490	2400/F(kHz)	300		
0.490 – 1.705	24000/F(kHz)	30		
1.705 – 30.0	30	30		
30 – 88	100	3		
88 – 216	150	3		
216 - 960	200	3		
Above 960	500	3		

#### 3.2.2. Measuring Instruments

See list of measuring instruments of this test report.


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 15 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

3.2.3. Test Procedures

- 1. The EUT was placed on a turntable with 0.8 meter above ground.
- 2. The EUT was set 3 meters from the interference receiving antenna, which was mounted on the top of a variable height antenna tower.
- 3. The table was rotated 360 degrees to determine the position of the highest radiation.
- 4. The antenna is a Bi-Log antenna and its height is adjusted between one meter and four meters above ground to find the maximum value of the field strength for both horizontal polarization and vertical polarization of the antenna.
- 5. For each suspected emission, the EUT was arranged to its worst case and then tune the antenna tower (from 1 m to 4 m) and turntable (from 0 degree to 360 degrees) to find the maximum reading.
- 6. Set the test-receiver system to Peak Detect Function and specified bandwidth with Maximum Hold Mode.
- 7. If the emission level of the EUT in peak mode was 3 dB lower than the limit specified, then testing will be stopped and peak values of EUT will be reported, otherwise, the emissions will be repeated one by one using the quasi-peak method and reported
- 8. Emission level (dBuV/m) = 20 log Emission level (uV/m)
- 9. Corrected Reading: Antenna Factor + Cable Loss + Read Level - Preamp Factor = Level

#### 3.2.4. Test Setup of Radiated Emission



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 16 of 21 Report Issued Date: Oct. 26, 2011

Report No.: FD170707-03

Report Version : Rev. 01



#### 3.2.5. Test Result of Radiated Emission




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 17 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



23~24°C Test Mode: Mode 1 Temperature: 45~46% Test Engineer: Kai Wang **Relative Humidity: Test Distance:** 3m Polarization : Vertical GSM850 (GPRS 8) Idle + Bluetooth Idle + GPS Rx + TC + Adapter **Function Type:** #7 is System Simulator Signal which can be ignored. Remark: 97 Level (dBuV/m) Date: 2011-08-25



Site : 03CH06-HY Condition : FCC CLASS-B HF-ANT\_090824 YERTICAL

Model	Mode I

	Freq	Level	Over Limit	Limît Line		Intenna Factor		Preamp Factor	Ant Pos	Table Pos	Remark
	MHz	dBu∛/m	dB	<b>dB</b> u∛/m	dBu₹	dB/m	dВ	dB	cm	deg	
1 @	56. 73	36.01	-3.99	40.00	59.81	6.95	0.92	31.68	100	96	Peak
2 !	128.28	38.17	-5.33	43.50	56.64	11.85	1.38	31.70	50000	505000	Peak
	264.09	40.61	-5.39	46.00	57.51	12.89	1.91	31.70	90000	535353	Peak
3 ! 4 5 6 7	311.90	39.05	-6.95	46.00	54.83	13.75	2.10	31.64	500000	5157651	Peak
5	358.80	36.94	-9.06	46.00	51.41	14.82	2.26	31.56	50000	5157657	Peak
6	824.30	38.05	-7.95	46.00	45.56	20.98	3, 45	31.94	50000	505050	Peak
7	880.30	33.11			39.69	21.46	3.68	31.72	500000	535353	Peak
8	2844.00	43.16	-30.84	74.00	59.24	33.07	5.92	55.06	50000	5555	Peak
9	4614.00	47.18	-26.82	74.00	60.75	34.90	7.84	56.30	505050	505050	Peak
8 9 10	6904.00	49.40	-24.60	74.00	59.73	36, 26	10.55	57.14			Peak
11	7372.00	49.57	-24.43	74.00	59.14	36.15	11.22	56.94	100		Peak
12	10684.00		-24.80	74.00	56.70	37.94	10.70	56.14	50000		Peak
13	11666.00		-25.11	74.00	54.88	38.35	10.88	55. 21			Peak

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 18 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



4. List of Measuring Equipment

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Due Date	Remark
EMI Test Receive	R&S	ESCI 7	100724	9kHz~7GHz	Aug. 22, 2011	Aug. 21, 2012	Conduction (CO05-HY)
Two-LISN	R&S	ENV216	11-100081	9KHz – 30MHz	Dec. 03, 2010	Dec. 02, 2011	Conduction (CO05-HY)
Two-LISN	R&S	ENV216	11-100080	9KHz – 30MHz	Dec. 01, 2010	Nov. 30, 2011	Conduction (CO05-HY)
AC Power Source	APC	APC-1000W	N/A	N/A	N/A	N/A	Conduction (CO05-HY)
GPS Station	Pendulum	GSG-54	N/A	N/A	N/A	N/A	Conduction (CO05-HY)
Spectrum Analyzer	R&S	FSP40	100057	9KHz-40GHz	Oct. 25, 2010	Oct. 24, 2011	Radiation (03CH06-HY)
EMI Test Receiver	R&S	ESVS10	834468/003	20MHz-1000M Hz	May 10, 2011	May 09, 2012	Radiation (03CH06-HY)
Bilog Antenna	SCHAFFNER	CBL6112B	2885	30MHz -2GHz	Oct. 31, 2010	Oct. 30, 2011	Radiation (03CH06-HY)
Double Ridge Horn Antenna	EMCO	3117	00066583	1GHz~18GHz	Aug. 01, 2011	Jul. 31, 2012	Radiation (03CH06-HY)
Double Ridge Horn Antenna	Training Research	AH-0801	95119	8GHz~18GHz	Oct. 20, 2010	Oct. 19, 2011	Radiation (03CH06-HY)
SHF-EHF Horn Antenna	SCHWARZBE CK	BBHA 9170	BBHA917025 1	15GHz- 40GHz	Oct. 18, 2010	Oct. 17, 2011	Radiation (03CH06-HY)
Pre Amplifier	Agilent	8449B	3008A01917	1GHz- 26.5GHz	Apr. 14, 2011	Apr. 13, 2012	Radiation (03CH06-HY)
Amplifier	Agilent	310N	186713	9KHz~1GHz	Apr. 14, 2011	Apr. 13, 2012	Radiation (03CH06-HY)
GPS Station	T&E	GS-50	N/A	N/A	N/A	N/A	-
GPS Station	pendulum	GSG-54	N/A	N/A	N/A	N/A	-
System Simulator	R&S	CMU200	117591	N/A	Oct. 18, 2010	Oct. 17, 2011	-

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 19 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

### 5. Uncertainty of Evaluation

#### **Uncertainty of Conducted Emission Measurement (150 kHz ~ 30 MHz)**

	Uncerta		
Contribution	dB	Probability Distribution	u(X <sub>i</sub> )
Receiver Reading	0.10	Normal (k=2)	0.05
Cable Loss	0.10	Normal (k=2)	0.05
AMN Insertion Loss	2.50	Rectangular	0.63
Receiver Specification	1.50	Rectangular	0.43
Site Imperfection	1.39	Rectangular	0.80
Mismatch	+0.34 / -0.35	U-Shape	0.24
Combined Standard Uncertainty Uc(y)		1.13	
Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y))	2.26		

#### **Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)**

	Uncerta	Uncertainty of X <sub>i</sub>			
Contribution	dB	Probability Distribution	u(X <sub>i</sub> )		
Receiver Reading	0.41	Normal (k=2)	0.21		
Antenna Factor Calibration	0.83	Normal (k=2)	0.42		
Cable Loss Calibration	0.25	0.25 Normal (k=2)			
Pre-Amplifier Gain Calibration	0.27	Normal (k=2)	0.14		
RCV/SPA Specification	2.50	Rectangular	0.72		
Antenna Factor Interpolation for Frequency	1.00	Rectangular	0.29		
Site Imperfection	1.43	Rectangular	0.83		
Mismatch	+0.39 / -0.41	U-Shape	0.28		
Combined Standard Uncertainty Uc(y)	1.27				
Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y))	2.54				

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 20 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



#### **Uncertainty of Radiated Emission Measurement (1 GHz ~ 40 GHz)**

	Uncertai	Uncertainty of X <sub>i</sub>				
Contribution	dB	Probability Distribution	u(X <sub>i</sub> )	C <sub>i</sub>	C <sub>i</sub> * u(X <sub>i</sub> )	
Receiver Reading	±0.10	Normal (k=2)	0.10	1	0.10	
Antenna Factor Calibration	±1.70	Normal (k=2)	0.85	1	0.85	
Cable Loss Calibration	±0.50	Normal (k=2)	0.25	1	0.25	
Receiver Correction	±2.00	Rectangular	1.15	1	1.15	
Antenna Factor Directional	±1.50	Rectangular	0.87	1	0.87	
Site Imperfection	±2.80	Triangular	1.14	1	1.14	
Mismatch Receiver VSWR $\Gamma$ 1 = 0.197 Antenna VSWR $\Gamma$ 2 = 0.194 Uncertainty = 20Log(1- $\Gamma$ 1* $\Gamma$ 2)	+0.34 / -0.35	U-Shape	0.244	1	0.244	
Combined Standard Uncertainty Uc(y)	2.36					
Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y))	4.72					

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : 21 of 21
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01

### Appendix A. Photographs of EUT

Please refer to Sporton report number EP170707-03 as below.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : A1 of A1 Report Issued Date: Oct. 26, 2011

Report No.: FD170707-03

Report Version : Rev. 01

#### 1. External Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 1 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-03



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 2 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

#### 2. Photograph of Accessory

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03

**List of Accessory:** 

List of Accessory.							
	Specification of Accessory						
AC Adapter	Brand Name	CINCON ELECTRONICS					
AC Adapter	Model Name	TRG36A15 12E03					
Battery 1	Brand Name	DAP					
Dattery i	Model Name	VE026-8034					
Battery 2	Brand Name	DAP					
Dattery 2	Model Name	VE026-8035					
LCD Panel	Brand Name	SGD					
LCD Fallel	Model Name	GNTW70NNBA1E0					
Camera 1	Brand Name	DEMARREN					
Calliera i	Model Name	Q5M03A					
WWAN Module	Brand Name	Sierra Wireless					
WWWAIN WIOGUIE	Model Name	MC8355					
WLAN Module	Brand Name	Summit Data Communications					
VILAN WOULde	Model Name	SDC-PE15N					
Bluetooth Module	Brand Name	Bluegiga					
Bidetootii Woddie	Model Name	WT21-A					
Power Cord 1	Brand Name	QUAIL					
ower cold i	Model Name	1062.079(NAM032)					
Power Cord 2	Brand Name	QUAIL					
	Model Name	8002.079(NAM033)					
Power Cord 3	Brand Name	QUAIL					
	Model Name	9657.079(NAM034)					

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 3 of 20 Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

Report No.: EP170707-03



Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 4 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-03




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 5 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 6 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 7 of 20 Report Issued Date : Oct. 24, 2011

Report Version : Rev. 01

#### 3. Internal Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 8 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 9 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 10 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 11 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 12 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 13 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-03




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 14 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 15 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 16 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010


Report No.: EP170707-03



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 17 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Report No.: EP170707-03




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 18 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 19 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01

Brand Name: DAP / Model Name: 9000WBWV1 / Marketing Name: M9010

Report No.: EP170707-03




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 IC: 4609A-9000WBWV1 Page Number : 20 of 20
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01



## Appendix B. Setup Photographs

#### <Conducted Emission>




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : B1 of B3
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



Report No. : FD170707-03

#### <Radiated Emission>

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : B2 of B3
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01



Report No. : FD170707-03





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWV1 Page Number : B3 of B3
Report Issued Date : Oct. 26, 2011
Report Version : Rev. 01