DAP Technologies LTD

4535 Boul. Wilfrid-Hamel, Suite 100, Quebec G1P 2J7, Canada Tel: 480-319-3199; Fax: 418-681-7734

Date: March 31, 2013

SUBJECT: FCC Application for FCC ID: T5M-M1010WBWW

We, DAP Technologies LTD, attest this device FCC ID: T5M-M1010WBWW only supports GPRS/WCDMA/CDMA2000 operation below

GPRS/EGPRS: Cellular, PCS band
WCDMA/HSPA: Band II, IV, V
CDMA2000/EV-Do: BC0, BC1

The implemented software permanently limits the LTE functionality of N7NMC7355 embedded in this tablet, and user cannot find any other mean to re-enable LTE functionality.

Khalid Kidari