

Report No.: FD170707

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : B1 of B2 Report Issued Date: Oct. 24, 2011 Report Version : Rev. 01



Report No. : FD170707

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : B2 of B2
Report Issued Date : Oct. 24, 2011
Report Version : Rev. 01