1. External Photograph of EUT

Brand Name: DAP Technologies / Model Name: MT1010

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW Page Number : 2 of 43
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW

Page Number : 3 of 43 Report Issued Date : Mar. 15, 2013

Report Version : Rev. 01

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW Page Number : 4 of 43
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: DAP Technologies / Model Name: MT1010

Report No.: EP312810

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	LITEON
	Model Name	PA-1061-0
Battery 1	Brand Name	Dynapack
	Model Name	GT101C
Battery 2	Brand Name	Pegatron Corporation
	Model Name	GS4150-02
WWAN Module	Brand Name	Sierra Wireless Inc.
	Model Name	MC7355
WLAN Module	Brand Name	Qualcomm Atheros, Inc.
	Model Name	AR5B22

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW Page Number : 6 of 43
Report Issued Date : Mar. 15, 2013

Report Version : Rev. 01

Report No.: EP312810



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW Page Number : 7 of 43

Report Issued Date : Mar. 15, 2013

Report Version : Rev. 01



Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW


Page Number

: 8 of 43

Report Issued Date : Mar. 15, 2013

: Rev. 01 Report Version

Report No.: EP312810



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW IC: 4609A- M1010WBWW Page Number : 9 of 43
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01