

DAP Technologies LTD. 875, Blvd. Charest West, # 200 Quebec, Qc. Canada, G1N 2C9

Phone:

+1 418 681 7833

Fax:

+1 418 681 7734

www.daptech.com

February 4th, 2010

Equipment Autorisation Division Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

FCC ID:T5M5000B2, T5M5000B3, T5M5000B4, T5M5000B5, T5M5000B6, T5M5000B7, T5M5000B8 & T5M5000B9.

Tune-up procedure

All devices falling under the stated above FCCID do not have any tune-up procedure. Furthemore, our WWAN device doesn't permit the power/frequency tune-up.

Regards,

Eric Renaud

Project manager

e.renaud@daptech.com