


Appendix B. Setup Photographs


<Radiated Emission>

<X Plane>

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW Page Number : B1 of B2
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: FG312810B




<Y Plane>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M -M1010WBWW Page Number : B2 of B2
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: FG312810B