

Test report No. : 26JE0089-HO
Page : 9 of 16
Issued date : June 8, 2006
FCC ID : T82TWF600R

APPENDIX 1: Photographs of test setup

Conducted Emission





UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 26JE0089-HO Page : 10 of 16 : June 8, 2006 **Issued date** FCC ID : T82TWF600R

Radiated Emission









UL Apex Co., Ltd. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone Facsimile : +81 596 24 8116 : +81 596 24 8124


Test report No. : 26JE0089-HO
Page : 11 of 16
Issued date : June 8, 2006
FCC ID : T82TWF600R

Worst Case Position (Horizontal: Z-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124