INTERTEK TESTING SERVICE

Report No: HK12030374-1

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 5343



FCC ID: T96PORTABL

INTERTEK TESTING SERVICE

Report No: HK12030374-1

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Model: 5343



FCC ID: T96PORTABL