

MARK-IV VHF BROADBAND SIGNAL BOOSTER M4BBDAV FCC ID: TCJ- M4BBDAV

REVISION 0 SUBMITTED BY:

CANAM TECHNOLOGY, INC.



FCC ID: TCJ-M4BBDAV
MODEL: M4BBDAV

CANAM TECHNOLOGY, INC. (CTI)
MARK-IV VHF BROADBAND SIGNAL BOOSTER M4BBDAV

FCC LABEL SAMPLE

I. Label Pictures



FCC Label Location

Model and Serial Number Label Location

Figure 1 – Labels Location Rear Panel details

Part 90 Signal Boosters THIS IS A 90.219 CLASS B DEVICE

WARNING. This is **NOT** a **CONSUMER** device. It is designed for installation by **FCC LICENSEES** and **QUALIFIED INSTALLERS.** You **MUST** have an **FCC LICENSE** or express consent of an FCC Licensee to operate this device. You **MUST** register Class B signal boosters (as defined in 47 CFR 90.219) online at **www.fcc.gov/signal-boosters/registration.** Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Figure 2 – FC C ID Label design example

NOTE: This is a FCC Label sample.