

Continental Wireless, Inc.

2355 Merritt Drive / Suite #200 Garland TX 75041 Tel 972-926-7443/800-527-2000 Fax #972-926-0624

Attn: Reviewing EngineerFederal Communications Commission7435 Oakland Mills Road

RE: Label for R5000-O-4.9, FCC ID TIG R5000-O-49

To Whom It May Concern:

Columbia, MD 21046

This document contains a drawing for the label, including Part 15 Information for the R5000-O-4.9 wireless router, FCC ID TIG R5000-O-49..

Please contact me if there is any information you may need.

Sincerely,

Gary Weber Vice President Continental Wireless, Inc. Figure One – Label Information Infinet Wireless - R5000 - O - 4.9 4.9 GHz Wireless Router FCC ID: TIG R5000-0-49 XXXXXXXXX Serial: XXXXXXXXX MAC: FCC Certification
This device complies with Part 15 of the FCC rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation. InfiNet InfiNet Wireless Router 4.9 5000 s/n 004962