



PAGE NUMBER : C4 OF C47
ISSUED DATE : Oct 13, 2008







PAGE NUMBER : C5 OF C47
ISSUED DATE : Oct 13, 2008






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : C6 OF C47
ISSUED DATE : Oct 13, 2008






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : C7 OF C47
ISSUED DATE : Oct 13, 2008
































TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : C13 OF C47
ISSUED DATE : Oct 13, 2008











843032-05







SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : C16 OF C47
ISSUED DATE : Oct 13, 2008


























PAGE NUMBER : C21 OF C47
ISSUED DATE : Oct 13, 2008



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : C22 OF C47
ISSUED DATE : Oct 13, 2008