





Photographs of EUT












SPURTON LAB.



Report No.:641226-02











Report No.:641226-02






Report No.:641226-02










Report No.:641226-02







Report No.:641226-02















Report No.:641226-02



















Report No.:641226-02






































































Report No.:641226-02



SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973

PAGE NUMBER : 38 OF 44

ISSUED DATE : Jul. 19, 2016

