


ATTACHMENT F.


- INTERNAL PHOTOS -

Report No.: HCTR0910FR06 1/13






Report No.: HCTR0910FR06 2/13








Report No.: HCTR0910FR06 3/13






Report No.: HCTR0910FR06 4/13









Report No.: HCTR0910FR06 5/13








Report No.: HCTR0910FR06 6/13








Report No.: HCTR0910FR06 7/13









Report No.: HCTR0910FR06 8/13









Report No.: HCTR0910FR06 9/13








Report No.: HCTR0910FR06 10/13








Report No.: HCTR0910FR06 11/13





Report No.: HCTR0910FR06 12/13





Report No.: HCTR0910FR06 13/13