


ATTACHMENT F.

- INTERNAL PHOTOS -


Report No.: HCTR1002FR24 1/24








Report No.: HCTR1002FR24 2/24








Report No.: HCTR1002FR24 3/24








Report No.: HCTR1002FR24 4/24








Report No.: HCTR1002FR24 5/24






Report No.: HCTR1002FR24 6/24





Report No.: HCTR1002FR24 7/24








Report No.: HCTR1002FR24 8/24








Report No.: HCTR1002FR24 9/24






Report No.: HCTR1002FR24 10/24








Report No.: HCTR1002FR24 11/24






Report No.: HCTR1002FR24 12/24









Report No.: HCTR1002FR24 13/24







Report No.: HCTR1002FR24 14/24








Report No.: HCTR1002FR24 15/24








Report No.: HCTR1002FR24 16/24








Report No.: HCTR1002FR24 17/24





Report No.: HCTR1002FR24 18/24





Report No.: HCTR1002FR24 19/24







Report No.: HCTR1002FR24 20/24







Report No.: HCTR1002FR24 21/24








Report No.: HCTR1002FR24 22/24







Report No.: HCTR1002FR24 23/24







Report No.: HCTR1002FR24 24/24