

ATTACHMENT A.

- ID LABEL INFORMATION AND LOCATION PHOTOS -

Report No.: HCTR1005FR15 1/4



1.1 ID Label Information

Following is a copy of the label that will be placed on the rear side of the cabinet. Both the FCC ID and compliance statement are included in the product label

Figure 1.1 PRODUCT LABEL

FCC Model No : AVN-215TDL
IC Model No : AVN-215TDLL
FCC ID : TQ8-AVN-215TDL
IC : 5074A-AVN215TDLL

EUT Type : CAR AVN

Serial No :

This device complies with part 15 of the FCC Rules.

Operation is subject to the following two conditions:
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,


Including interference that may cause undesired operation.

HYUNDAI MOBIS CO.,LTD.

80-9, MABOOK-RI, GUSEONG-EUP, YONGIN-SHI, GYUNGGI-DO, 449-912 SOUTH KOREA

MADE IN KOREA

Report No.: HCTR1005FR15 2/4





FCC Model No : AVN-212TDL
IC Model No : AVN-212TDLL
FCC ID : TQ8-AVN-215TDL
IC : 5074A-AVN215TDLL

EUT Type : CAR AVN

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and

(2) this device must accept any interference received, Including interference that may cause undesired operation.

HYUNDAI MOBIS CO.,LTD.

80-9, MABOOK-RI, GUSEONG-EUP, YONGIN-SHI, GYUNGGI-DO, 449-912 SOUTH KOREA

MADE IN KOREA

FCC Model No : AVN-214TDL
IC Model No : AVN-214TDLL
FCC ID : TQ8-AVN-215TDL
IC : 5074A-AVN215TDLL

EUT Type : CAR AVN

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and

(2) this device must accept any interference received, Including interference that may cause undesired operation.

HYUNDAI MOBIS CO.,LTD.

80-9, MABOOK-RI, GUSEONG-EUP, YONGIN-SHI, GYUNGGI-DO, 449-912 SOUTH KOREA

MADE IN KOREA

Report No.: HCTR1005FR15 3/4



1.2 Label Location Drawing

The label shown shall be permanently affixed at a conspicuous location on the device and be readily visible to the user at the time purchase. (Labeling requirements per 2.925)

Figure 1.2 LABEL LOCATION



Report No.: HCTR1005FR15 4/4