ADB40C2AN

FCC Information

Hyundai MOBIS Co., Ltd.

FCC ID: TQ8-ADB40C2AN Contains ID: LHJ-CASAN

This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

MANUFACTURED BY HYUNDAI MOBIS

PRODUCT LABEL

