

ATTACHMENT A.

- ID LABEL INFORMATION AND LOCATION PHOTOS -





1.1 ID Label Information

Following is a copy of the label that will be placed on the rear side of the cabinet. Both the FCC ID and compliance statement are included in the product label

Figure 1.1 PRODUCT LABEL

FCC Model : AC110CSAN
IC Model : AC110CSKN
FCC ID : TQ8-AC110CSAN
IC : 5074A-AC110CSKN

EUT Type : **CAR AUDIO**

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and

(2) this device must accept any interference received,

Including interference that may cause undesired operation.

HYUNDAI MOBIS CO., LTD.

80-9, Mabook-Dong, Giheung-Gu, Yongin-Shi, Gyunggi-Do,446-912 South Korea

MADE IN KOREA

FCC ID: TQ8-AC110CSAN/ IC: 5074A-AC110CSKN

FCC Model : AC110CSGG
IC Model : AC1A0CSKN
FCC ID : TQ8-AC110CSAN
IC : 5074A-AC110CSKN

EUT Type : CAR AUDIO

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, Including interference that may cause undesired operation.

HYUNDAI MOBIS CO., LTD.

80-9, Mabook-Dong, Giheung-Gu, Yongin-Shi, Gyunggi-Do,446-912 South Korea

MADE IN KOREA

FCC Model : AC110CSGE
IC Model : AC110CSKN
FCC ID : TQ8-AC110CSAN
IC : 5074A-AC110CSKN

EUT Type : CAR AUDIO

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and

- (2) this device must accept any interference received,
- Including interference that may cause undesired operation.

HYUNDAI MOBIS CO., LTD.

80-9, Mabook-Dong, Giheung-Gu, Yongin-Shi, Gyunggi-Do,446-912 South Korea

MADE IN KOREA



FCC ID: TQ8-AC110CSAN/ IC: 5074A-AC110CSKN

FCC Model : AC110CSGN
IC Model : AC110CSKN
FCC ID : TQ8-AC110CSAN
IC : 5074A-AC110CSKN

EUT Type : **CAR AUDIO**

Serial No :

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, Including interference that may cause undesired operation.

HYUNDAI MOBIS CO., LTD.

80-9, Mabook-Dong, Giheung-Gu, Yongin-Shi, Gyunggi-Do,446-912 South Korea

MADE IN KOREA



1.2 Label Location Drawing

The label shown shall be permanently affixed at a conspicuous location on the device and be readily visible to the user at the time purchase. (Labeling requirements per 2.925)

Figure 1.2 LABEL LOCATION

