

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (37) of (203)

# KCTL


## UNII-1 / 802.11n HT20 / Low ch.




## UNII-2A / 802.11n HT20 / Low ch.




## UNII-1 / 802.11n HT20 / Mid ch.




## UNII-2A / 802.11n HT20 / Mid ch.



## UNII-1 / 802.11n HT20 / High ch.



## UNII-2A / 802.11n HT20 / High ch.



This test report shall not be reproduced, except in full, without the written approval

KCTL-TIR001-003/2

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (38) of (203)

# KCTL


## UNII-2C / 802.11n HT20 / Low ch.




## UNII-3 / 802.11n HT20 / Low ch.




## UNII-2C / 802.11n HT20 / Mid ch.




## UNII-3 / 802.11n HT20 / Mid ch.



## UNII-2C / 802.11n HT20 / High ch.



## UNII-3 / 802.11n HT20 / High ch.



This test report shall not be reproduced, except in full, without the written approval

KCTL-TIR001-003/2

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (39) of (203)

# KCTL


## UNII-1 / 802.11n HT40 / Low ch.




## UNII-2A / 802.11n HT40 / Low ch.



## UNII-1 / 802.11n HT40 / High ch.



## UNII-2A / 802.11n HT40 / High ch.



This test report shall not be reproduced, except in full, without the written approval

KCTL-TIR001-003/2

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (40) of (203)

# KCTL


## UNII-2C / 802.11n HT40 / Low ch.




## UNII-3 / 802.11n HT40 / Low ch.




## UNII-2C / 802.11n HT40 / Mid ch.



## UNII-3 / 802.11n HT40 / High ch.



## UNII-2C / 802.11n HT40 / High ch.



Blank

# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (41) of (203)

# KCTL


## UNII-1 / 802.11ac VHT20 / Low ch.




## UNII-2A / 802.11ac VHT20 / Low ch.




## UNII-1 / 802.11ac VHT20 / Mid ch.




## UNII-2A / 802.11ac VHT20 / Mid ch.



## UNII-1 / 802.11ac VHT20 / High ch.



## UNII-2A / 802.11ac VHT20 / High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0044


Page (42) of (203)

# KCTL


## UNII-2C / 802.11ac VHT20 / Low ch.




## UNII-3 / 802.11ac VHT20 / Low ch.




## UNII-2C / 802.11ac VHT20 / Mid ch.



## UNII-3 / 802.11ac VHT20 / Mid ch.



## UNII-2C / 802.11ac VHT20 / High ch.



## UNII-3 / 802.11ac VHT20 / High ch.

