


Appendix C. Set up Photograph

Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Feb. 21, 2006
Report Version : Rev. 02





SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Feb. 21, 2006

Report Version : Rev. 02



Radiation Emission

Mode 1~3



FRONT VIEW

REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Feb. 21, 2006
Report Version : Rev. 02





Mode 4



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Feb. 21, 2006
Report Version : Rev. 02