Mr. Fujimoto:

In order for processing of this application (FCC ID: TSNMOXLR) to continue, the following issue(s) will have to be addressed:

- 1) The FCC ID in the test report and the one stated in the 731 form are different. Please clarify the correct FCC ID that is to be used and submit any corrections.
- 2) The block diagram submitted does not appear to match the schematics submitted. Please submit the appropriate block diagram or schematic.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is TSNMOXLR-1.

Best Regards,

Mike Christensen Evaluator Compatible Electronics TCB Phone: 714-579-0500

Fax: 714-579-1850 www.celectronics.com