
Test setup photos of K830BT

1. Conducted Emission Test setup

Connect to PC Mode



2. Radiated Emission Test (Blow 1GHz)



3. Radiated Emission Test (Above 1GHz)

On Mode

