Helen Zhao

Subject: FW: FW: eXS Inc., FCC ID: TTFN01A1206, Assessment NO.: AN05T5357

Hi Helen.

I have uploaded the missing documents, new user manual with statements, revised confidentiality letters, and DTS reports with all the data showing.

Regarding the max power, I have included a table in the user manual that lists the maximum power output at each frequency. The table shows that only the mid channel channel 6 is at the maximum Chung Nam power levels. Channels 1-5 and 7-11 are at the bandedge levels.

best regards

Tom

```
>Hello Tom,
> I reviewed both applications. Below are my comments:
> >1) eXS Inc., FCC ID: TTFN01A1206, Assessment NO.: AN05T5357,
> >Question #1: Please submit an Agent Authorization letter.
> >Question #2: The user manual does not contain user information as >specified in FCC15.105(b), 15.21, and RF exposure statement as >specified in 15.247(i).
> >Question #3: The test data on page 6 of the test report is >incomplete. Please submit 11g Middle channel, and 11a (5745-5805MHz) >at all L, M, H channels.
> >Question #4: Operational Description from Chung Nam application >filing is now in this filing. Please include Operational Description >in the confidentiality letter.
> >Thank you,
> Helen
```

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.