Appendix A. Test Photos

Report No. : FR571429

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01

Report No. : FR571429



FCC Test Report Report No.: FR571429



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz




Report No. : FR571429

: A4 of A6


: Rev. 01

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version





For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6

Report Version

: Rev. 01


Report No. : FR571429




FCC Test Report

Report No. : FR571429

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01