


Date: 28.JAN.2018 09:18:36


CH78 Hopping on mode (Upper) _1Mbps




Date: 28.JAN.2018 09:19:10










Date: 28.JAN.2018 09:06:13




Date: 28.JAN.2018 09:06:20

Report No.: BTL-FCCP-1-1801C180 Page 106 of 117








Date: 28.JAN.2018 09:06:27


CH39 (10 Harmonic of the frequency) _1Mbps




Date: 28.JAN.2018 09:07:04








Date: 28.JAN.2018 09:07:11




Date: 28.JAN.2018 09:07:18











Date: 28.JAN.2018 09:08:42



Date: 28.JAN.2018 09:08:50










Date: 28.JAN.2018 09:08:57












Date: 28.JAN.2018 09:29:20










Date: 28.JAN.2018 09:41:51


CH78 Hopping on mode (Upper) _3Mbps




Date: 28.JAN.2018 09:42:25










Date: 28.JAN.2018 09:25:14




Date: 28.JAN.2018 09:25:21

Report No.: BTL-FCCP-1-1801C180 Page 113 of 117








Date: 28.JAN.2018 09:25:28


CH39 (10 Harmonic of the frequency) _3Mbps




Date: 28.JAN.2018 09:26:49







Date: 28.JAN.2018 09:26:56




Date: 28.JAN.2018 09:27:03






CH78 (10 Harmonic of the frequency) _3Mbps




Date: 28.JAN.2018 09:29:51



Date: 28.JAN.2018 09:29:58







Date: 28.JAN.2018 09:30:05

Report No.: BTL-FCCP-1-1801C180