


Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A5 : Rev. 01

Report No. : FR591830

Report Version



FCC C2PC Test Report



Report No. : FR591830


SPORTON INTERNATIONAL INC. Page No. : A2 of A5 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973






Report No. : FR591830



Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A5

Report Version : Rev. 01






Report No.: FR591830



Radiated above 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A5

Report Version

: Rev. 01



FCC C2PC Test Report



Report No. : FR591830

: A5 of A5

: Rev. 01

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-3273456 Report Version

FAX: 886-3-3270973