



BABT Balfour House, Churchfield Road Walton on Thames Surrey, KT12 4TD United Kingdom Telephone: +44 (0)1932 251200

Fax: +44 (0)1932 251201

Direct Dial: +44 (0)1932 251247 E-mail: Bill.Wilson@babt.com Website: www.babt.com

Ref: US000119

23 May 2006

To FCC

Evaluation of Loc8tor Handheld FCC id: TUW-LOH11

I have assessed the above referenced submission for the Loc8tor Handheld and found it to be compliant.

The following were noted and resolved during the evaluation.

1: Test Results

A number of clarifications were requested concerning the test results, these were all addressed and the report re-issued.

2. RF Exposure

It was confirmed that the device is categorically excluded from routine evaluation and below the low threshold.

3. FCCID

It was initially unclear whether the FCCID included the hyphen, the client confirmed that the hyphen was included.

4. Other exhibits

Two versions of the Loc8tor Handheld are described in the user manual, the client confirmed that they are electrically identical.

There were issues concerning the photographs and confidentiality request. These were all addressed and the documents revised.

Yours sincerely

Bill Wilson

Technical Certifier For BABT TCB

h/EW/hon