



BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 4TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Ref: US000120

23 May 2006

To FCC

Direct Dial: +44 (0)1932 251247 E-mail: Bill.Wilson@babt.com Website: www.babt.com

# Evaluation of Loc8tor Tag FCC id: TUW-LOT11

I have assessed the above referenced submission for the Loc8tor Tag and found it to be compliant.

The following were noted and resolved during the evaluation.

#### 1: Test Results

A number of clarifications were requested concerning the test results, these were all addressed and the report re-issued.

## 2. RF Exposure

It was confirmed that the device is categorically excluded from routine evaluation and below the low threshold.

## 3. FCCID

It was initially unclear whether the FCCID included the hyphen, the client confirmed that the hyphen was included.

### 4. Other exhibits

Two versions of the Loc8tor Tag are described in the user manual, the client confirmed that they are electrically identical.

There were issues concerning the photographs and confidentiality request. These were all addressed and the documents revised.

Yours sincerely

Bill Wilson

Technical Certifier For BABT TCB